

XYZ Mining Company

Site-Specific Hazard Training

Welcome to XYZ Mining Company mining and milling operation. To make your visit a safe one please follow the safety procedures listed below.

A. GENERAL SAFETY

1. Keep away from moving equipment.
2. Observe all traffic signs and signals.
3. Never turn your back on moving equipment.
4. Stay in sight of equipment operators.
5. Stay away from conveyor belts and moving machinery.
6. Do not get on or off from moving equipment
7. Do not smoke in 'No Smoking Areas' or near flammables or combustibles.
8. Follow your guides instructions to the letter.
9. Sign in upon arrival at the island.
10. Rock samples are provided at the cannery. Do not pick up samples.

B. PERSONAL PROTECTION

1. Hard hats must be worn at all times unless inside office areas.
2. Safety glasses must be worn in designated areas and eye hazard areas.
3. Steel toe shoes must be worn at all times. (Except in office)
4. Hearing protection must be worn in noisy or loud areas and where posted.
5. Respirators must be worn in dusty areas.
6. Self-rescuers must be with you when underground.
7. If your visit requires the use of a helicopter, follow the pilots instructions to the letter.
8. For the safety of all persons from the Alaska Brown Bear do not leave food scraps or wrappers laying around, bring it back to the cannery for disposal.

C. EMERGENCY PROCEDURES

1. Report all injuries to your guide.
2. Ask your guide to explain escape and evacuation procedures for each area you visit. If evacuation is necessary, follow your guides instructions.
3. Report all fires as soon as possible.
4. Blasting operations are conducted at the mine. Do not wander away from your guide.

D. UNGUIDED TOUR

Once you are familiar with a work area, if you are required to work you must follow these rules at all times. You must be familiar with all rules and procedures and follow them to the letter.

E. MILL AREA

1. The mill operation uses some chemicals and toxic substances.
 - Do not enter unauthorized areas unless you have permission.
 - Do not handle any materials without permission.
 - Respirator protection and special clothing are required where posted.
2. Obey all signs posted throughout the mill area.

F. MINE AND PIT AREAS

1. Never stand, park, or work on top of bank edges where there is danger of caving.
2. Never park or stand at the base of highwall banks. Slides or falls of materials may occur.
3. Never work between equipment or machinery and the pit wall or bank where the equipment or machinery would hinder your escape from falls or slides of the bank.
4. Make certain by signal or other means that equipment operators are aware of your presence.
5. Do not park or stand behind equipment due to the operator's limited visibility.
6. Do not enter flagged areas unless authorized.

G. MISCELLANEOUS

1. Electrical hazards may be encountered-do not handle power cables or perform any work on electrical equipment unless you are authorized to do so.
2. Do not look at the flash from welding or cutting operations.
3. Do not handle materials which might cause hand or finger injuries, without suitable hand protection.
4. Always be aware of back and rib conditions.
5. Do not take chances.

Name _____

Company _____

Date Trained _____

Signature _____

Instructor _____